

Agenda Report

TO: CITY COUNCIL

DATE: June 18, 2007

THROUGH: FINANCE COMMITTEE

FROM: CITY MANAGER

SUBJECT: CITY HALL SEISMIC RETROFIT PROJECT -APPROVAL OF CONTINGENCY ADJUSTMENTS AND CHANGE ORDER #12 TO THE GENERAL CONTRACTOR

RECOMMENDATION

It is recommended that the City Council:

- Approve the allocation of \$1,268,820 from Project Contingency for unforeseen conditions and project activities, as identified in Attachment #1, discovered during the retrofit of City Hall, thereby reducing the amount of Project Contingency from \$4,160,311 to \$2,891,491; and
- 2) Authorize the City Manager to execute Change Order #12 to Contract Number 18,768-1 with Clark Construction Group-California, LP (Clark Construction) for increases in scope of work due to unforeseen conditions and project activities discovered during the retrofit of City Hall, as identified in Attachment #1, thereby increasing the contract amount by \$1,268,820 from \$83,216,859 to \$84,485,679.

CITY HALL RESTORATION OVERSIGHT COMMITTEE ADVISORY DIRECTION

On June 13, 2007, the City Hall Restoration Oversight Committee reviewed the topics of contingency adjustments contained in General Contractor Change Order #12 .The Committee concurred that the recommendations under Change Order #12 are reasonable and consistent with ongoing construction activities of similar projects. Thus it was recommended that the City Council authorize the allocation of \$1,268,820 from Project Contingency which includes an increase to Contract Number 18,768-1 with Clark Construction by \$1,268,820.

BACKGROUND

On January 31, 2005, the City Council authorized the City Manager to execute the City Hall general contractor contract (Contract Number 18,768) with Clark Construction in the amount of \$79,899,000. Eleven change orders and the associated contingency adjustments have been approved by City Council to date bringing the current contract amount to \$83,216,859. Change Order #12 represents a settlement of one hundred and fifteen different cost items that resolve changes in the scope of work. These items include unforeseen field conditions, conflicts between the "original" drawings and the "as-builds", required additions/changes and items that were not a part of the contract drawings. This cumulative change order is detailed in the List of Contingency Adjustments (Attachment #1).

PROJECT CONTINGENCY ADJUSTMENTS

The proposed Change Order #12 referenced below proposes to transfer a total of \$1,268,820 from Project Contingency, resulting in a Project Contingency balance of \$2,891,491 as follows:

| 1) | Beginning Project Contingency (1/31/05) | \$8,642,014 |
|----|---|--------------|
| 2) | City Council-Approved Contingency Adjustments | (4,481,703) |
| | Current Project Contingency Balance | 4,160,311 |
| 3) | Proposed Contingency Adjustments (6/18/07) | |
| | A. General Contractor (Change Order #12) | _(1,268,820) |
| 4) | Project Contingency Balance (6/18/07) | \$2,891,491 |

The project is 98% completed, and 67% of the contingency funds have been expended.

GENERAL CONTRACTOR CHANGE ORDER #12

During ongoing construction, the general contractor has encountered unforeseen conditions as listed in Attachment #1. Contract Change Order #12 increases the scope of work to Contract Number 18,768-1 with Clark Construction in the amount of \$1,268,820 thereby increasing the contract sum to \$84,485,679 as follows:

| 1) | Current City Council-Approved Contract Award | \$83,216,859 | |
|----|--|--------------|--|
| 2) | Proposed Change Order #12 (6/18/07) | \$1,268.820 | |
| | Proposed Contract Sum: | \$84,485,679 | |

SCHEDULE CHANGES

To date, no changes in the milestone completion dates have been authorized. The overall project is on schedule and unchanged since the award of the general contractor bid. The general contractor's date of Substantial Completion remains July 9, 2007, and the date of Final Completion remains October 8, 2007. The contractor proceeded with the accelerated schedule approved by City Council in Change Order #9 to allow incremental occupancy of the building by the City which began on April 30, 2007.

FISCAL IMPACT

The City Hall project budget of \$117,594,083 has not changed since the award date of the general contractor's contract on January 31, 2005. The proposed contingency adjustment in the amount of \$1,268,820 reduces the total City Hall project contingency from \$4,160,311 to \$2,891,491.

Respectfully submitted,

THIA J. City Manager

Prepared by:

Steven L. Wright

Assistant City Engineer Department of Public Works

Approved by:

Martin Pastucha Director Department of Public Works

Attachments: Attachment #1 - List of Contingency Adjustments

| | A. | B. | C. | E. |
|--------|-------------|---|--------------|--|
| | | Description | Total | Comments |
| 1 | 1. | Beginning Contingency Balance 1/31/05 | \$ 8,642,014 | |
| 2 | | | | · · · · · · · · · · · |
| 3 | | | | |
| 4 | 11. | City Council Approved Contingency Adjustments | (4,481,703) | |
| 5 6 | III. | Proposed Contract Adjustments 6/18/07 (tentative) | | |
| 7 | Α. | Proposed General Contractor Adjustments 6/18/07 (Change Order #12). | | |
| 8 | CCD 43 | Re-coordination costs for 1st floor South. | VOID | Voided by General Contractor. |
| 9 | CCD 51 | Install fountain piping from point of connection outside of fountain to the fountain pump room in the basement and connect fountain equipment | | City requested change. |
| 10 | CCD 51 | and controllers. Install fountain piping and equipment. Amount released from contract schedule of values (line item #000010 for \$66,000). | (151,750) | CCD #51 - \$66,000 will be offset by construction allowances and \$85,750 will be offset by project contingency. |
| 11 | CCD 115 | Modifications to roof louvers. | 66,000 | Voided by General |
| | | | VOID | Contractor. |
| 12 | CCD 138 | Bulletin #3 - Modifications to 1st, 2nd and 3rd floor shearwalls Northeast and Southeast ends of | 1 | Unforeseen field condition. |
| 13 | CCD 152 | the building. Replacement of sidewalk @ Union Street. | (51,416) | Voided by General Contractor. |
| 14 | CCD 159 | Changes to stair nosing from epoxy to paint. | | Voided by General Contractor. |
| 15 | CCD 167 | Changes to perimeter footing demolition. | | Voided by General Contractor. |
| 16 | CCD 194 | Basement South corridor drywall column enclosure adjustments that required modification to ductwork and plumbing lines. | | Insufficient information on the architectural drawings. |
| 17 | CCD 197 | Change fire control access panels from 24" sq to 30" sq. | | Voided by General Contractor. |
| 18 | CCD 206 | Structural issues at basement rotunda. | | Voided by General Contractor. |

| | A. | B. | C. | Ε. |
|----|----------|--|-----------|-------------------------------|
| | | Description | Total | Comments |
| 19 | CCD 210 | Replace sidewalk along Thurgood Marshall. | | Voided by General |
| | | | VOID | Contractor. |
| 20 | CCD 211 | Corrective action to extensive paint chips and | | Unforeseen field |
| | 1 | failures due to years of existing paint build-up in | | condition. |
| | | rooms S305 and S307 and modify the ceiling in | | |
| | | room S305 due to piping. | (16,588) | |
| 21 | CCD 213 | Install walkways over ductwork and piping in the | | Unforeseen field |
| | | North and South attic. | (23,771) | condition. |
| 22 | CCD 213 | Install walkways over ductwork. Amount released | | CCD #213 - \$20,485 will |
| | | from contract schedule of values (line item | | be offset by construction |
| | | #000040 for \$7,771; line item #000070 for | | allowance and \$3,286 |
| | | \$11,672 and line item #000090 for \$1,042). | | will be offset by project |
| | | | | contingency. |
| | | | 20,485 | |
| 23 | CCD 215 | Re-feed the historical light fixture at 1st floor | | Unforeseen field |
| | | North stair #1 required to cut the concrete wall | | condition. |
| | | and re-patch. | (2,541) | 4 = |
| 24 | CCD 220 | Install sprinkler heads in (4) stair towers at level 3 | | Voided by General |
| | | | • · · · - | Contractor. |
| 25 | CCD 228 | Corrective action to existing plaster walls to match | | Unforeseen field |
| | | adjacent surfaces to rooms S211 office, S215 | | condition. |
| | | corridor, S218 office and S111 vestibule. | | |
| | | | (29,653) | • • • • • • • • • • • • • • • |
| 26 | CCD 236 | Install a cased opening between rooms S206 and | | City requested change. |
| | | S209. | (6,520) | |
| 27 | CCD 237 | Remove water cooler from S246A and replace (8) | | City requested change. |
| | | wood wainscot panels at S246A, S233, S237, | | |
| | CCD 240 | S241 and S246. | (20,063) | |
| 28 | 1000 240 | Add wood trim/panels to rooms S227 shared | | City requested change. |
| 29 | CCD 241 | office & S237 shared office. | (5,632) | . |
| 29 | CCD 241 | Corrective action to plaster wall finish and picture | | City requested change. |
| | | frame moldings in rooms S246 & S241 to match | (00.007) | 1 |
| 30 | CCD 244 | adjacent finishes. | (39,387) | 1· · · |
| 30 | UUU 244 | Drywall box out for exposed fiber wrap columns | | Insufficient information |
| | | (18) in the basement north and south. | (04.55.4) | on the architectural |
| 31 | CCD 246 | Added controls for EE 0.5 interlacked demonstra | (24,554) | drawings. |
| | 000 240 | Added controls for EF-0-5 interlocked dampers. | | Voided by General |
| 32 | CCD 249 | Add removable grating for the 2 sump pumps in | | Contractor. |
| 52 | 000 249 | | (4 007 | City requested change. |
| | | the North equipment well. | (1,827) | // |

| | A. | В. | C. | E. |
|-----|---------|--|----------|---|
| - · | | Description | Total | Comments |
| 33 | CCD 251 | Bulletin #11 - additional electrical, data and phone | | City requested change. |
| | | jacks for modular furniture and provide electrical | | |
| | | labor to connect power feeds to modular furniture. | | |
| | | | (67,177) | |
| 34 | CCD 253 | Add 260 lineal feet of metal base on 1st floor | | Unforeseen field |
| | | North/South and 3rd floor North/South. | (83,315) | condition. |
| 35 | CCD 258 | Modifications to cable tray (2nd flr south, 1st flr | | Unforeseen field |
| | | north) to allow access to mechanical valves | | condition. |
| | | above. | (5,472) | |
| 36 | CCD 259 | Plaster repair work to rooms S246 Conference | | Voided by General |
| | | room, S244 Mayor's office, S237 Office and S233 | | Contractor. |
| | | Office. | VOID | |
| 37 | CCD 260 | Added missing wood trim for corridor vision lights | | City requested change. |
| 1 | 1 | room S215. | (8,578) | |
| 38 | CCD 265 | Location of post tension threadbars installed at | | Insufficient information |
| | | the west jacket wall interferes with the location of | | on the structural |
| 1 | | the embeds required additional expansion | | drawing. |
| | | anchors. | (1,484) | |
| 39 | CCD 266 | Basement door changes. | | Voided by General |
| | | | VOID | Contractor. |
| 40 | CCD 267 | Close and seal existing holes and penetrations in | | City requested change. |
| } | | S225 vault room, remove chalkboard and patch | | |
| | | wall to match adjacent surface in room S245 | | |
| | | Mayor's office. | (5,513) | ter a construction of the |
| 41 | CCD 268 | Remove existing damaged wood base & repatch | | Insufficient information |
| | | walls on 4th floor to accept rubber base. | | on the architectural |
| | | | (14,838) | drawings. |
| 42 | CCD 269 | Remove and replace plywood subfloor at dais | | Unforeseen field |
| | | platform in council chambers and add backing for | | condition. |
| | | AV monitor in room S245 reception. | (18,450) | |
| 43 | CCD 277 | Add exhaust fan interlocks to HVAC units | | Insufficient information |
| | | | | on the |
| | | | | electrical/mechanical |
| | 000 070 | | (14,000) | drawings. |
| 44 | CCD 278 | Add guardrail and grating to diagonal steel | | Unforeseen field |
| | | platform at roof access by 3rd floor South skylight | | condition. |
| 45 | | | (3,430) | |
| 45 | CCD 279 | Exterior plaster patch above copper flashing on | | Unforeseen field |
| | | the 4th/5th floor balcony roofs, stair tower no. 3/4 | | condition. |
| 1 | L | and around added steel at 3rd floor balconies. | (13,216) | |
| 46 | CCD 286 | Change catch basin filter inserts from Flowmaster | | Voided by General |
| | | to Bioclean Environmental. | VOID | Contractor. |

| | A. | B. | C. | E. |
|----|---------|---|---------------------------------------|--------------------------|
| | | Description | Total | Comments |
| 47 | CCD 287 | Adjust locations of installed mirrors at rest rooms | | Insufficient information |
| | | N132 and S127. | | on the architectural |
| | | | (1,047) | drawings. |
| 48 | CCD 289 | Modifications to the framing and plaster finish at | | Insufficient information |
| | | the arcade expansion joints North and South end. | | on the architectural |
| | | | (28,000) | drawings. |
| 49 | CCD 293 | Removal of mulch from courtyard and | | Unforeseen field |
| ļ | | offload/plant (2) 60" box palm trees. | (3,877) | condition. |
| 50 | CCD 296 | Install light pole footings, 2 on Garfield and 10 in | · · · · · · · · · · · · · · · · · · · | Unforeseen field |
| Į. | | the courtyard. | (13.396) | condition. |
| 51 | CCD 297 | Add bird deterrents at main entry capitals, clock | | City requested change. |
| | | and at all 4 stair towers. | (6,558) | |
| 52 | CCD 298 | Unused number. | | Voided by General |
| | | | | Contractor. |
| 53 | CCD 299 | Add new door and frame at S037A (SE ramp) / | | City requested change. |
| | | N125 (office), replace transom at door S017A | | |
| | | (SW ramp) with metal studs/plaster and revise | | |
| | | door hardware on doors N103C (elevator lobby | | |
| | | closet) / S235D (corridor). | (7,508) | |
| 54 | CCD 300 | Change door and frame S016A from 7'-0" to a 6'- | | Unforeseen field |
| | | 8" to clear concrete beam and piping. | (3 236) | condition. |
| 55 | CCD 302 | Corrective action to plaster walls to match | ((0,-0,0) | City requested change. |
| | | adjacent surfaces at 3rd floor lobby, corrective | · · · · | |
| | | action for paint at curb below skylight at 4th floor, | | |
| 1 | | revise wood trim at open office S325, refinish | | |
| | | walls in vault S340, refinish walls at bottom of | | |
| | | stair #7. | (22,518) | |
| 56 | CCD 303 | Remove and re-install wood shoe at the wood | (22,310) | City requested change. |
| | | base to allow installation of linoleum floor at all | | City requested change. |
| | | floor levels. | (14,760) | 1 |
| 57 | CCD 304 | Concrete/brick demolition required for the | (14,700) | Insufficient information |
| | | expansion joint and collector steel at the arcade | | on the architectural |
| | | tie-in to existing bldg North/South. | (16 120) | drawings. |
| 58 | CCD 305 | Replace wood casing around access panel at | (10,139) | City requested change. |
| | | room 402 open office, corrective action to plaster | | City requested change. |
| | | walls in room S111 break rm to match adjacent | | |
| | | surfaces. | (6.049) | |
| 59 | CCD 306 | Install new wood wainscot southwest corner, TV | (6,048) | Unforeseen field |
| Ĩ | | monitor supports, add steel angle to stiffen | | |
| 1 | } | balusters in room S249. | (2.025) | condition/City requested |
| 60 | CCD 307 | Isolation valve for irrigation supply line. | (3,835) | change. |
| ľ | | | | Voided by General |
| | 1 | | | Contractor. |

| | A. | В. | C. | E. |
|----|---------|---|---------------------------------------|--------------------------|
| | | Description | Total | Comments |
| 61 | CCD 309 | Remove and replace ceiling in rm S109 | · · · · · · · · · · · · · · · · · · · | Unforeseen field |
| | | storage/vault and corrective action to extensive | | condition. |
| | | paint chips in S216 break rm and S217 storage | | |
| | | rm. | (11,183) | |
| 62 | CCD 310 | Add flashing at the curb in the moat. | | Voided by General |
| | | č | VOID | Contractor. |
| 63 | CCD 311 | Corrective action to exterior concrete pilaster to | | Unforeseen field |
| | | plaster, corrective action to plaster soffits and | | condition. |
| 1 | | columns at the arcade tie-in to the building North | | |
| | | and South. | (42,224) | |
| 64 | CCD 312 | Revise courtyard elevations including regrading | | Insufficient information |
| } | | and adjusting catch basins for proper drainage. | | on the civil drawings. |
| | | and adjusting batter batter of proper arainage. | (48,750) | |
| 65 | CCD 314 | Add epoxy dowels, 1" x 3" flat bar to stiffen 5/8" | (, | Insufficient information |
| | | plate modify curb heights to 4" for the (4) | | on the architectural |
| | | courtyard ramps. | (7 464) | drawings. |
| 66 | CCD 315 | Garfield stair demolition. | | Voided by General |
| | | | | Contractor. |
| 67 | CCD 316 | Modify lectern height in Council Chamber room. | | City requested change. |
| | | | (5,368) | |
| 68 | CCD 317 | 2nd floor South VAV (HVAC) conflict between | (0,000) | Insufficient information |
| | | schedule and drawings required the coil and the | | on the mechanical |
| l | | sheetmetal changed out. | (6.263) | drawings. |
| 69 | CCD 319 | Remove and replace 3rd floor lobby protection to | (0,203) | City requested change. |
| | | allow City's conservator to clean pavers, protect | | City requested change. |
| | | council chamber furniture for carpet installation, | | |
| | | protection of linoleum floors and elevator operator | | |
| | | assistance for modular furniture/City movers. | | |
| | | | (17,081) | |
| 70 | CCD 320 | Provide access holes to allow installation of rebar | (17,001) | Unforeseen field |
| | | in the sub-basement South perimeter wall. | | condition. |
| | | in the sub-basement South perimeter wall. | (2 100) | |
| 71 | CCD 321 | Reposition (1) oak tree in the courtyard. | (3,180) | |
| 72 | CCD 322 | Add two openings in grates over generator 7 fire | (1,451) | City requested change. |
| 12 | | pump for fuel fill requirements. | (4 540) | Required by Pasadena |
| 73 | CCD 323 | B1 wall in basement north conflicts with shaft wall | (1,513) | Unforeseen field |
| 1 | 000 323 | | | |
| 1 | | for the boiler flue and required modifications. | 10.400 | condition. |
| 74 | CCD 325 | Additional (10) concrete analy repairs on stair | (3,183) | |
| ' | 000 323 | Additional (19) concrete spall repairs on stair | | Insufficient information |
| | | treads at all 4 stair towers. | (0.000) | on the architectural |
| L | | | (8,698) | drawings. |

| | A. | B. | C. | E. |
|----|---------|---|-------------|-------------------------------------|
| | | Description | Total | Comments |
| 75 | CCD 327 | 1st floor South modification to ductwork due to | | Voided by General |
| | | soffit changes. | VOID | Contractor. |
| 76 | CCD 328 | Modifications to ductwork with existing beam from | | Unforeseen field |
| | | 1st floor to basement North. | (2,964) | condition. |
| 77 | CCD 329 | Reposition light fixtures for maintenance in rooms | | Unforeseen field |
| | | 402 and N104. | (1,405) | condition. |
| 78 | CCD 331 | Added additional emergency 20 amp lighting | | Unforeseen field |
| | | circuits for the historical fixtures in the council | | condition. |
| | | chamber rm. | (12,270) | |
| 79 | CCD 332 | Removal of concrete haunches at the isolation | | Unforeseen field |
| | | level in (2) stair towers to allow bldg movement. | (6,739) | condition. |
| 80 | CCD 333 | Unused number. | - , | Voided by General |
| | | | VOID | Contractor. |
| 81 | CCD 336 | Demolition & Clean-up of the walls in Vault N102. | | Voided by General |
| | | | VOID | Contractor. |
| 82 | CCD 339 | Corrective action to plaster walls in 1st and 2nd | | City requested change. |
| | | floor elevator lobby's N103/N203, conference | - - - | |
| | | room S219, offices S233/S237 to match adjacent | | |
| | | surfaces. | (14,323) | |
| 83 | CCD 340 | Add 3/8" pins (8) per bay at the topping slab at | | Unforeseen field |
| | | the arcade for the slab to bond to the | | condition. |
| | | waterproofing. | (1,198) | |
| 84 | CCD 341 | Modify existing doors S260 and S248A and | | Unforeseen field |
| | | fabricate new wood transoms to match. | (2,432) | condition. |
| 85 | CCD 342 | Modifications to handrail/guardrail at the boiler | | Insufficient information |
| | | room/equipment well at the basement and provide | | on the architectural |
| | | (2) new handrails at the handicap ramps in the | | drawing. |
| | | courtyard. | (31,713) | _ |
| 86 | CCD 343 | Refinishing of the wood wainscot in rooms S249 | | Unforeseen field |
| | | & S246. | (16 744) | condition. |
| 87 | CCD 344 | Painting existing plaster base to look like wood in | | Unforeseen field |
| | | rooms N104, N109, N120, N122, N123 and N124. | (4.400) | condition |
| | CCD 345 | | (1,168 | condition. |
| 88 | CCD 345 | Modifications to return plenum into Council | | Unforeseen field |
| | | Chambers requiring air grilles, access panels and | | condition. |
| 00 | CCD 346 | wood panels. | (6,038 | · · · · |
| 89 | 000 340 | Re-plaster walls at (4) stair towers basement | (22.000 | City requested change. |
| | 000 247 | level. | (36,968 | · · · · · · · · · · · · · · · · · · |
| 90 | CCD 347 | Courtyard urn plinth footing detail changes. | | Voided by General |
| L | 1 | l | VOIL | Contractor. |

| | A. | В. | C. | E. |
|------|---------|--|---|--------------------------|
| | | Description | Total | Comments |
| 91 | CCD 348 | Add 19 exit signs required per field walk with Fire | | Required by Pasadena |
| 1 | | Marshall, 3rd flr dome, 1st flr stair towers 1 & 2, | | Fire. |
| | | basement north & south, 2nd fir north & south and | • | |
| | | 3rd flr south. | (16,974) | |
| 92 | CCD 349 | Modify existing beam to allow head clearance at | | Unforeseen field |
| | | stair tower 2 basement level. | (14,846) | condition. |
| 93 | CCD 350 | Replace existing damaged wood base and install | | Insufficient information |
| 1 | | wood covers for abandoned cabinets in rooms | | on the architectural |
| | | S201, S202, S203 and S204. | (6,491) | drawing. |
| 94 | CCD 351 | Add backing in existing wall for grab bar in | · - · · · · · · · · · · · · · · · · · · | Unforeseen field |
| | | restroom S305 and demo/rebuild plaster clg in | | condition. |
| | | S103 vestibule for fire protection. | (6,012) | |
| 95 | CCD 352 | Replace sidewalk at Union, Euclid and Thurgood | | City requested change. |
| | | Marshall street. | (72,000) | |
| 96 | CCD 353 | Unused number. | | Voided by General |
| | 1 | | | Contractor. |
| 97 | CCD 354 | Pour concrete ring around (8) light well cans in | | Insufficient information |
| | | the courtyard. | | on the landscape |
| | | | (1 133) | drawing. |
| 98 | CCD 355 | Add mirror in restroom S133; install brackets for | | City requested change. |
| | | monitors for rooms S245, S246 & S249; repair | | engrequeeted enange. |
| 1 | | work to quarry tile at 3rd floor lobby area. | | |
| | | | (10,564) | |
| 99 | CCD 356 | Add wood nailers at stair risers (stair #6 & 7) for | (10,004) | City requested change. |
| | | carpet installation. | (1,830) | |
| 100 | CCD 357 | Audiovisual overtime to complete council | (1,000) | Voided by General |
| | | chamber room. | | Contractor. |
| 101 | CCD 358 | Add t-bar ceiling soffits at rooms S018 | | Unforeseen field |
| | | (classroom) & S027 (break room) to conceal | | condition. |
| 1 | | piping. | (1,520) | |
| 102 | CCD 359 | Install (12) deal trays in municipal counter and | (1,020) | City requested change. |
| | | drill holes in council chamber desks for electrical. | | ony requested change. |
| | | difficition in council chamber desks for electrical. | (2,050) | |
| 103 | CCD 361 | Install new doors and hardware at the 5th and 6th | | City requested change. |
| 1.00 | | floor levels. | | |
| 104 | CCD 362 | Re-striping of handicap parking on Garfield near | (3,316) | City requested change. |
| 104 | 0000002 | Union Street and adding 8 truncated domes to | | City requested change. |
| | | H/C curb ramps. | (5.222) | |
| 105 | CCD 363 | Add 90 If of guardrail at Garfield ramp, extend | (5,322) | Insufficient information |
| | | | 1 | |
| | | pickets & bottom rail @ Garfield ramp at isolation | 1 | on the architectural |
| | | joint & extend (4) guardrails @ Euclid ramp top | (24.000) | drawing. |
| L | 1 | landing required by ADA. | (31,026) | Ч |

| | Α. | В. | C. | E. |
|-----|---------|---|-------------|--------------------------|
| | | Description | Total | Comments |
| 106 | CCD 364 | Fabricate and install metal covers at openings | | Insufficient information |
| | | near Euclid stairs. | | on the architectural |
| | | | (3,494) | drawing. |
| 107 | CCD 365 | Provide 7 dummy cylinders, 5 hold back locks, 19 | · · · · · · | City requested change. |
| | | floor stops and 3 hand locks at doors in the | | |
| | | building. | (3,428) | |
| 108 | CCD 366 | Change the concrete finish from sack/patch and | | City requested change. |
| | | broom finishes to exposed finish with integral | | |
| | | color at the walls/ steps and handicap ramps at | | |
| | | Euclid street and the handicap ramp on Garfield. | (62,765) | |
| 109 | CCD 367 | Add 2 x 2 angle plate and additional reinforced | (02,700) | Unforeseen field |
| | | steel at the Garfield entrance steps. | (3 766) | condition. |
| 110 | CCD 368 | Add splash blocks in courtyard. | (0,700) | Voided by General |
| | | Add splash blocks in courtyard. | VOID | Contractor. |
| 111 | CCD 369 | Concrete/grout at courtyard light pole bases & | | Voided by General |
| 1 | | wells lights. | | Contractor. |
| 112 | CCD 370 | Remove, restore and reinstall City Hall letters at | | Insufficient information |
| | | the arcade and add hasps at moat gates. | | on the architectural |
| | | | (3.505) | drawing. |
| 113 | CCD 371 | Revise base cabinet at kitchen sink for ADA | | Insufficient information |
| | | accessibility at room S240. | | on the architectural |
| | | | (1.310) | drawing. |
| 114 | CCD 372 | Add pavers in lieu of splash blocks in courtyard. | 1 . X17-277 | Voided by General |
| | | / ··· / ··· / ··· / ··· / ··· / ··· / ··· / ··· / / ··· / / ··· / / ··· / / ··· / / ··· / / ··· / / ··· / / ··· | | Contractor. |
| 115 | CCD 373 | Add electrical for 7 work stations, add | | City requested change. |
| | | conduit/cable for the DWP meter, dial up modem | | |
| | | access for lighting control, for the fire alarm | | |
| | | systems and add 2 outlets 3rd floor break rooms. | | |
| | | | (11,341) | |
| 116 | CCD 374 | Add Ladder Supports @ Stair Tower #1 | | Unforeseen field |
| | | | (1,317) | condition. |
| 117 | CCD 375 | Install glass (8 pieces) in transoms in corridor | | City requested change. |
| | | S215, add window film to door S111A (vestibule) | | |
| | | and add window shade in room N212 (office). | | |
| | | | (4,114) | |
| 118 | CCD 376 | Fabricate and install shelf to hold Trash Lift | | Insufficient information |
| | | Control Box. | | on the architectural |
| | | | (3,876 | drawing. |
| 119 | CCD 377 | Reframe a portion of a metal stud wall in the | | Unforeseen field |
| | | basement corridor south to allow the rerouting of | | condition. |
| | | the 6" main fire line. | (4,664 |) |

| | Α. | B. | C. | E. |
|------------|-------------|---|-------------|--------------------------|
| | | Description | Total | Comments |
| 120 | CCD 378 | Revise emergency lighting circuitry for the 1st & | | Unforeseen field |
| | | 2nd floor loggias, main entrance stairs and (4) | | condition. |
| | | stair towers. | (16,261) | |
| 121 | CCD 379 | Replace door at storage room in stair no. 1 | | City requested change. |
| | | basement level. | (1,058) | • |
| 122 | CCD 380 | Provide power to (3) control panels, air flow | | Insufficient information |
| | | switches, relays and monitoring for the refrigerant | | on the |
| | | alarm system required for the leak detection | | electrical/mechanical |
| | | system. | (19,679) | drawings. |
| 123 | CCD 381 | Painting additional handrail brackets @ Stair #6. | | Voided by General |
| 1 | | <u></u> | VOID | Contractor. |
| 124 | CCD 382 | Remove and replace 15 l.f. of existing damaged | | City requested change. |
| | | curb at Euclid Street. | (2,393) | 1 |
| 125 | | | | |
| 126 | | Total General Contractor Adjustment (Change | | |
| | | Order #12) | (1,268,820) | |
| 127 | | | | |
| 128 | B. | Proposed City Contracted Adjustments 6/18/07. | | |
| 1100 | | | | |
| 129 130 | C. | Draw a set Drais at Drais at Advisor and a C/40/07 | | · · · |
| 130 | 0. | Proposed Project Budget Adjustments 6/18/07. | - | |
| 131 | | | | |
| 132 | | | | - ··· - · · - |
| 133 | | | | |
| 134 | iv. | Total Cantingonov Adjustment (6/18/07 tentative) | | + |
| 135 | v . | Total Contingency Adjustment (6/18/07 tentative) | (1,268,820) | ÷ · |
| 136 | v. | Ending Contingency Balance (6/18/07 tentative) | | ··· |
| 130 | ♥. | | 2,891,491 | |
| 137 | - · | | 2,051,491 | |
| | <u> </u> | | I | |