







**PASADENA CITY HALL - EXTERIOR BUILDING RESTORATION
CAST STONE FIGURE BUILDING REPAIRS**








ITEM 2.B.



**PASADENA CITY HALL - EXTERIOR BUILDING
COPPER LANTERNS/TOWER REPAIRS/RESTORATION**

ITEM 2C.









**PASADENA CITY HALL - EXTERIOR PLASTER REPAIR
BUILDING CLEANING AND PAINTING**




ITEMS 2.D./2.E.




PASADENA CITY HALL - ROTUNDA CLOCK REHABILITATION - ITEMS 2.F.



HISTORIC SIDEWALK CONDITIONS




HISTORIC SIDEWALK - DAMAGE/TEMPORARY REPAIRS



HISTORIC BRICK SIDEWALK - GARFIELD AVENUE ENTRANCE



PASADENA CITY HALL - HISTORIC SIDEWALK RESTORATION ITEM 2.G.



SCALE 1/8" = 1'-0"
 Proposed Planting Plan
 COURTYARD


EIP

PUBLIC WORKS DEPARTMENT
 1980




PASADENA CITY HALL - COURTYARD LANDSCAPING


ITEM 3.A.




Original Courtyard with Landscape Urns (1927)



Original 1927 Planter-Urn (Missing)








Original Planter 1927 Urn (Missing)



PASADENA CITY HALL - EXTERIOR SITE WORK URN REPLACEMENT


ITEM 3.B




ITEM 3.C

PASADENA CITY HALL - FLAGPOLE RESTORATION



Garfield Av.
Existing Condition





Garfield Av. - Rendering
New H/P Ramp




Renderings - Euclid Av.
H/P Ramps








Garfield Av. H/P Ramp Plans







Euclid Avenue H/P Ramp Plans



PASADENA CITY HALL - GARFIELD AND EUCLID H/P RAMPS-ITEM 3.D./3.E.









PASADENA CITY HALL - ORNAMENTAL METAL WORK - ITEM 3.G.



EXTERIOR SITEWORK - COURTYARD FOUNTAIN RESTORATION - ITEM 4.






EXTERIOR SITEWORK - COURTYARD FOUNTAIN - FOUNTAIN VIEWS







2nd Floor Existing Historic Elevator - Interior Space





2nd Floor Existing Small Elevator at Council Chambers



PASADENA CITY HALL - ELEVATORS- REHABILITATION/NEW - ITEM 5.




CITY COUNCIL CHAMBERS - DAIS




TECHNOLOGY UPGRADE OPTIONS - (LA CITY HALL

PASADENA CITY HALL - INTERIOR WORK COUNCIL CHAMBERS DAIS
ITEM 6.A./6.B.







FIRST FLOOR PLAN



THIRD/FOURTH FLOOR PLANS



BASEMENT PLAN



SECOND FLOOR PLAN



PASADENA CITY HALL - PLANS FOR INTERIOR RESTORATION OF REMAINING EXISTING HISTORIC AREAS
 ITEM 6.D.2.