

ATTACHMENT D:
Inventory of Properties

Historic Highlands Inventory

NO	DIR	STREET	APN	DATE	ARCHITECT/BUILDER	STATUS	POSSIBLE ALTERATIONS/NOTES	ARCHITECTURAL STYLE	NOTES
916		ATCHISON ST	5848-035-001	1939	Economy Housing Corp.	contributing	porch	Spanish Colonial Revival	
925		ATCHISON ST	5848-036-022	1929	Louis Steinhauer (architect/contractor)	contributing	narrow separate parcel; same address as adjacent lot	Spanish Colonial Revival	porch enlarged in 1940
930		ATCHISON ST	5848-035-004	1923	W.J. Hogan and Son (architect/contractor)	contributing	windows	Spanish Colonial Revival	
930		ATCHISON ST	5848-035-002			contributing	windows	English Vernacular	
935		ATCHISON ST	5848-036-020	1923		contributing	windows	Arts and Crafts	
940		ATCHISON ST	5848-035-005	1925	F.R. Finch (architect/contractor)	contributing	windows	Arts and Crafts	
947		ATCHISON ST	5848-036-019	1910	Foss Designing and Building Company (contractor)	contributing	windows	Spanish Colonial Revival	
950		ATCHISON ST	5848-035-006	1925		contributing	windows	Spanish Colonial Revival	
955		ATCHISON ST	5848-036-018	1921		contributing	windows	Spanish Colonial Revival	
960		ATCHISON ST	5848-035-007	1917	Craig/McKinsey	contributing	windows; doors; porch	Arts and Crafts	
969		ATCHISON ST	5848-036-017	1924		contributing	porch	Colonial Revival	
976		ATCHISON ST	5848-035-008	1908	E.A.B.; Frank A. Crosby (builder)	contributing	windows	Arts and Crafts	
979		ATCHISON ST	5848-036-016	1908	Arch. Des. Co. / John Mushrush	contributing	windows	Arts and Crafts	
985		ATCHISON ST	5848-036-015	1953		contributing	windows	Minimal Traditional	
990		ATCHISON ST	5848-035-009	1913	Foss Designing and Building Company (contractor)	contributing	windows	Prairie	
1003		ATCHISON ST	5848-036-013	1907	Sylvanus Marston (architect)/S.W. Upton	contributing	windows	Arts and Crafts	
1006		ATCHISON ST	5848-035-010	1925		contributing	wall cladding	English Vernacular	
1024		ATCHISON ST	5849-020-001	1939		contributing	windows	Spanish Colonial Revival	
1025		ATCHISON ST	5849-019-020	1927	C.E. Randle (Builder)	contributing	windows	Spanish Colonial Revival	
1040		ATCHISON ST	5849-020-003	1928		contributing	windows; doors	Spanish Colonial Revival	
1043		ATCHISON ST	5849-019-018	1905		contributing	windows; doors	Spanish Colonial Revival	
1050		ATCHISON ST	5849-020-004	1926		contributing	windows	Craftsman Bungalow	
1059		ATCHISON ST	5849-019-017	1907		contributing	windows	Arts and Crafts	
1060		ATCHISON ST	5849-020-005	1927	Steinhauer	contributing	windows	Spanish Colonial Revival	
1377	N	CATALINA AVE	5848-030-016	1985		out of period	wall cladding	Spanish Colonial Revival	
1381	N	CATALINA AVE	5848-030-015	1922	W.N. McKee (builder)	contributing	wall cladding	Craftsman Bungalow	
1391	N	CATALINA AVE	5848-030-014	1905		contributing	wall cladding	Arts and Crafts	
1399	N	CATALINA AVE	5848-030-013	1980	Charles Edwards (builder)	out of period	windows; doors; wall cladding; porch	Arts and Crafts	Original house demo'd in 1980 (fire damage)
1407	N	CATALINA AVE	5848-030-012	1908		non-contributing	windows; doors; porch	Craftsman Bungalow	
1459	N	CATALINA AVE	5848-031-020	1916		contributing	windows; wall cladding	Craftsman Bungalow	
1462	N	CATALINA AVE	5849-024-003	1922		non-contributing	windows; doors; inappropriate addition	Craftsman Bungalow	
1465	N	CATALINA AVE	5848-031-019	1975		out of period	windows; doors; wall cladding; porch	Ranch	
1470	N	CATALINA AVE	5849-024-002	1920		non-contributing	windows; doors; wall cladding; porch	Craftsman Bungalow	
1476	N	CATALINA AVE	5849-024-001	1920		non-contributing	windows; doors; wall cladding; porch	Craftsman Bungalow	
1477	N	CATALINA AVE	5848-031-018	1922		contributing	windows	Spanish Colonial Revival	
1481	N	CATALINA AVE	5848-032-019	1902		non-contributing	doors; wall cladding; porch	Craftsman Bungalow	
1486	N	CATALINA AVE	5849-023-003	1914	Eben John Smith (architect and builder)	contributing	windows	Craftsman Bungalow	
1492	N	CATALINA AVE	5849-023-002	1914	Eben John Smith (architect and builder)	non-contributing	windows; wall cladding; porch	Craftsman Bungalow	
1525	N	CATALINA AVE	5848-033-024	1922		contributing	windows; wall cladding; porch	Craftsman Bungalow	
1535	N	CATALINA AVE	5848-033-023	1915	George P. Telling/James H. Gaut	contributing	windows	Prairie	
1544	N	CATALINA AVE	5849-022-030	1926		non-contributing	wall cladding; porch; inappropriate addition	Craftsman Bungalow	
1545	N	CATALINA AVE	5848-033-022	1921	George P. Telling/James H. Gaut	contributing	wall cladding; porch; inappropriate addition	Craftsman Bungalow	
1550	N	CATALINA AVE	5849-022-027	1963		out of period	appropriate addition	Craftsman Bungalow	
1551	N	CATALINA AVE	5848-033-021	1916	J. Cyril Bennett/GB Gilmour & CW Adel	contributing	narrow separate parcel; same address as adjacent lot	Craftsman Bungalow	
1551	N	CATALINA AVE	5848-033-020	1916		contributing	adjacent lot	Craftsman Bungalow	
1557	N	CATALINA AVE	5848-033-019	1929		contributing	windows; doors; porch	Craftsman Bungalow	Hidden by shrubs
1558	N	CATALINA AVE	5849-022-002	1921		non-contributing	windows; doors; porch	English Vernacular	
1615	N	CATALINA AVE	5848-034-020	1924		contributing	windows; doors; porch	Spanish Colonial Revival	
1616	N	CATALINA AVE	5849-021-026	1923		contributing	windows; doors; porch	Spanish Colonial Revival	
1625	N	CATALINA AVE	5848-034-019	1921		contributing	windows; doors; porch	Colonial Revival	
1626	N	CATALINA AVE	5849-021-025	1923		contributing	windows; doors; porch	Spanish Colonial Revival	
1632	N	CATALINA AVE	5849-021-002	1950		contributing	windows; doors; porch	Minimal Traditional	
1635	N	CATALINA AVE	5848-034-018	1929		contributing	windows; doors; porch	Craftsman Bungalow	

Historic Highlands Inventory

NO	DIR	STREET	APN	DATE	ARCHITECT/BUILDER	STATUS	POSSIBLE ALTERATIONS/NOTES	ARCHITECTURAL STYLE	NOTES
1695	N	CATALINA AVE	5848-035-012	1929		contributing		English Vernacular	
1700	N	CATALINA AVE	5849-020-023	1924		contributing	doors;porch	Spanish Colonial Revival	
1705	N	CATALINA AVE	5848-035-011	1928	J.O. Grace (architect)	contributing		Spanish Colonial Revival	
1710	N	CATALINA AVE	5849-020-002	1923		contributing		Spanish Colonial Revival	
1770	N	CATALINA AVE	5849-019-019	1926		contributing		Spanish Colonial Revival	1951 house added to existing garage for 1003 Alchison
1775	N	CATALINA AVE	5848-036-014	1951		contributing		Minimal Traditional	1003 Alchison
1385	N	CHESTER AVE	5849-009-014	1918		contributing		Craftsman Bungalow	Can't see
1386	N	CHESTER AVE	5849-007-014	1921		contributing		Spanish Colonial Revival	
1400	N	CHESTER AVE	5849-007-015	1914		contributing		Colonial Revival	
1405	N	CHESTER AVE	5849-009-013	1926		contributing	windows;doors	Colonial Revival	New dormer 1990
1414	N	CHESTER AVE	5849-007-016	1921		contributing	windows	English Vernacular	
1415	N	CHESTER AVE	5849-009-012	1926	Leonardi & Clauson (builder)	contributing	windows	Arts and Crafts	
1424	N	CHESTER AVE	5849-007-017	1914		non-contributing	windows;doors;porch;inappropriate addition	English Vernacular	
1425	N	CHESTER AVE	5849-009-011	1929		non-contributing	windows;doors;wall cladding;porch	Colonial Revival	
1435	N	CHESTER AVE	5849-009-010	1937		contributing	windows	Craftsman Bungalow	
1436	N	CHESTER AVE	5849-007-018	1915	D.M. Renton (architect & builder)	contributing		Colonial Revival	
1450	N	CHESTER AVE	5849-007-019	1912		contributing	windows;doors;wall cladding	Colonial Revival	
1451	N	CHESTER AVE	5849-009-009	1941		non-contributing	windows;doors;wall cladding	Minimal Traditional	
1460	N	CHESTER AVE	5849-007-020	1913		contributing		Minimal Traditional	
1461	N	CHESTER AVE	5849-009-008	1942		contributing		Minimal Traditional	
1468	N	CHESTER AVE	5849-007-021	1925		contributing		Tudor	
1471	N	CHESTER AVE	5849-009-006	1941		contributing		Minimal Traditional	
1475	N	CHESTER AVE	5849-009-005	1930		contributing		Spanish Colonial Revival	
1484	N	CHESTER AVE	5849-007-022	1921		contributing	windows;roof	Craftsman Bungalow	
1485	N	CHESTER AVE	5849-009-004	1927		contributing		English Vernacular	
1499	N	CHESTER AVE	5849-009-003	1924		contributing		English Vernacular	
1500	N	CHESTER AVE	5849-007-023	1914		contributing		Arts and Crafts	
1505	N	CHESTER AVE	5849-009-001	1951		contributing		Ranch	
1506	N	CHESTER AVE	5849-007-024	1947		contributing	cladding	Minimal Traditional	
911		ELIZABETH ST	5848-034-001	1917	J. B. Speicher (contractor)	contributing	doors	Colonial Revival	
920		ELIZABETH ST	5848-033-009			non-contributing	parking lot		
925		ELIZABETH ST	5848-034-002	1918	J.B. Speicher (contractor)	contributing		Craftsman Bungalow	
928		ELIZABETH ST	5848-033-010	1922		contributing		American Colonial Revival	
933		ELIZABETH ST	5848-034-003	1918	Daniel Shilling (contractor)	contributing		Craftsman Bungalow	
936		ELIZABETH ST	5848-033-011	1921		contributing	wall cladding;porch	Craftsman Bungalow	
943		ELIZABETH ST	5848-034-027	1911	Henry C. Deming (architect & builder)	contributing	wall cladding	Arts and Crafts	
944		ELIZABETH ST	5848-033-012	1915	Bert G. Shaffer (builder)	contributing		Arts and Crafts	
953		ELIZABETH ST	5848-034-026	1920		contributing	windows;wall cladding	Craftsman Bungalow	
954		ELIZABETH ST	5848-033-013	1913	D. Shilling & L.B. Luce (builder)	contributing		Craftsman Bungalow	
965		ELIZABETH ST	5848-034-025	1911	contractor/owner John E. Crum	non-contributing	windows;doors;porch	Craftsman Bungalow	
966		ELIZABETH ST	5848-033-014	1912	Will A. Taylor (builder)	contributing	wall cladding	Arts and Crafts	
973		ELIZABETH ST	5848-034-024	1910	E. J. Collins (builder)	contributing		Craftsman Bungalow	
974		ELIZABETH ST	5848-033-015	1907	James (J.or I.) Boone	contributing	windows	Craftsman Bungalow	
981		ELIZABETH ST	5848-034-023	1911	M.H. Bloss (builder)	contributing		Craftsman Bungalow	
984		ELIZABETH ST	5848-033-016	1926		contributing	windows;doors	Craftsman Bungalow	
997		ELIZABETH ST	5848-034-022	1921		contributing		Craftsman Bungalow	
998		ELIZABETH ST	5848-033-017	1925		contributing		Minimal Traditional	
999		ELIZABETH ST	5848-033-018	1925		contributing		English Vernacular	
1006		ELIZABETH ST	5849-021-024	1927		contributing		Spanish Colonial Revival	
1026		ELIZABETH ST	5849-022-001	1928		contributing	windows	Spanish Colonial Revival	
1031		ELIZABETH ST	5849-021-027	1905	H.L. Fabrick (builder)	contributing		Craftsman Bungalow	
1035		ELIZABETH ST	5849-021-024	1922		contributing		Craftsman Bungalow	
1038		ELIZABETH ST	5849-022-003	1912	H.L. Gaut & O.C. Williams (architect & builder)	contributing	windows	Craftsman Bungalow	
1050		ELIZABETH ST	5849-022-004	1912	Robert B. Snyder (architect & builder)	contributing	windows	Craftsman Bungalow	
1051		ELIZABETH ST	5849-021-023	1921		contributing		Colonial Revival	

Historic Highlands Inventory

NO	DIR	STREET	APN	DATE	ARCHITECT/BUILDER	STATUS	POSSIBLE ALTERATIONS/NOTES	ARCHITECTURAL STYLE	NOTES
1060		ELIZABETH ST	5849-022-005	1922		contributing	porch	Craftsman Bungalow	
1061		ELIZABETH ST	5849-021-022	1905	F. Westlake (builder)	contributing		Arts and Crafts	
1070		ELIZABETH ST	5849-022-006	1908		contributing		Craftsman Bungalow	
1075		ELIZABETH ST	5849-021-021	1912		contributing	porch	Craftsman Bungalow	
1082		ELIZABETH ST	5849-022-007	1908		contributing	doors	Craftsman Bungalow	
1089		ELIZABETH ST	5849-021-020	1908		contributing	doors	Craftsman Bungalow	
1090		ELIZABETH ST	5849-022-008	1922		contributing	doors	Spanish Colonial Revival	
1091		ELIZABETH ST	5849-021-019	1925		contributing	windows; doors	Craftsman Bungalow	Chimney repaired 1986
1104		ELIZABETH ST	5849-022-009	1922		non-contributing	doors; wall cladding	Craftsman Bungalow	
1105		ELIZABETH ST	5849-021-018	1955		contributing		Spanish Colonial Revival	
1111		ELIZABETH ST	5849-021-015	1925		contributing		Minimal Traditional	
1112		ELIZABETH ST	5849-022-010	1923		non-contributing	inappropriate addition; porch	Minimal Traditional	
1119		ELIZABETH ST	5849-021-014	1923		non-contributing	porch	Spanish Colonial Revival	
1120		ELIZABETH ST	5849-022-013	1923		contributing		Craftsman Bungalow	
1135		ELIZABETH ST	5849-013-014	1917	J. R. R. Riley (contractor)	contributing	windows; wall cladding	Craftsman Bungalow	
1144		ELIZABETH ST	5849-012-019	1917	J. R. R. Riley (contractor)	contributing	windows; wall cladding	Craftsman Bungalow	
1154		ELIZABETH ST	5849-012-018	1917	J. R. R. Riley (contractor)	contributing	windows; wall cladding	Craftsman Bungalow	
1155		ELIZABETH ST	5849-013-016	1917		contributing	wall cladding	Craftsman Bungalow	
1164		ELIZABETH ST	5849-012-007	1923		contributing		English Vernacular	
1165		ELIZABETH ST	5849-013-017	1921		contributing	wall cladding; porch	Craftsman Bungalow	
1177		ELIZABETH ST	5849-013-018	1981	Frick & Frick	out of period		Minimal Traditional	
1178		ELIZABETH ST	5849-012-006	1924		contributing		Spanish Colonial Revival	
1181		ELIZABETH ST	5849-013-019	1921		contributing		Craftsman Bungalow	
1182		ELIZABETH ST	5849-012-005	1914		contributing		Arts and Crafts	
1194		ELIZABETH ST	5849-012-004	1914		contributing	windows; appropriate addition	Craftsman Bungalow	Not visible
1195		ELIZABETH ST	5849-013-020	1914		contributing		Italian Renaissance Revival	
1203		ELIZABETH ST	5849-013-021	1922		contributing		Arts and Crafts	
1206		ELIZABETH ST	5849-012-003	1914		contributing		Craftsman Bungalow	
1221		ELIZABETH ST	5849-013-022	1921		contributing		Craftsman Bungalow	
1231		ELIZABETH ST	5849-005-028	1922		contributing		Craftsman Bungalow	
1240		ELIZABETH ST	5849-006-008	1924		contributing		Craftsman Bungalow	
1249		ELIZABETH ST	5849-005-025	1936		contributing	windows; porch	Spanish Colonial Revival	
1250		ELIZABETH ST	5849-006-009	1924		contributing	windows; doors	Minimal Traditional	
1259		ELIZABETH ST	5849-005-024	1925		contributing	windows; doors	Spanish Colonial Revival	
1260		ELIZABETH ST	5849-006-011	1923		contributing	windows; doors	Spanish Colonial Revival	
1269		ELIZABETH ST	5849-005-023	1924		contributing	windows; doors	Craftsman Bungalow	
1270		ELIZABETH ST	5849-006-012	1923		contributing	doors	Craftsman Bungalow	
1277		ELIZABETH ST	5849-005-022	1923		contributing	windows; doors	English Vernacular	
1278		ELIZABETH ST	5849-006-013	1923		contributing	porch	Spanish Colonial Revival	
1286		ELIZABETH ST	5849-006-007	1923		contributing	wall cladding	Craftsman Bungalow	
1287		ELIZABETH ST	5849-005-010	1925		non-contributing	porch; inappropriate addition	Spanish Colonial Revival	
1294		ELIZABETH ST	5849-006-006	1924		contributing	appropriate addition	Craftsman Bungalow	
1295		ELIZABETH ST	5849-005-011	1923		contributing		Spanish Colonial Revival	
1301		ELIZABETH ST	5849-005-012	1925		contributing	windows	Spanish Colonial Revival	
1304		ELIZABETH ST	5849-006-005	1924		contributing	doors	Craftsman Bungalow	
1320		ELIZABETH ST	5849-006-001	1924		contributing	wall cladding	Craftsman Bungalow	
1347		ELIZABETH ST	5850-012-002	1924		contributing		Spanish Colonial Revival	
1353		ELIZABETH ST	5850-012-003	1924		contributing		Craftsman Bungalow	
1363		ELIZABETH ST	5850-012-004	1925		contributing		English Vernacular	
1364		ELIZABETH ST	5850-013-002	1923		contributing		Craftsman Bungalow	
1371		ELIZABETH ST	5850-012-016	1922		contributing	doors	Craftsman Bungalow	
1372		ELIZABETH ST	5850-013-026	1928		contributing	roof	Craftsman Bungalow	
1379		ELIZABETH ST	5850-012-015	1925		contributing	windows	Spanish Colonial Revival	
1385	N	HOLLISTON AVE	5849-007-013	1925		contributing		Tudor	
1394	N	HOLLISTON AVE	5850-015-004	1946		contributing		Spanish Colonial Revival	
1401	N	HOLLISTON AVE	5849-007-012	1924		contributing		English Vernacular	

Historic Highlands Inventory

NO	DIR	STREET	APN	DATE	ARCHITECT/BUILDER	STATUS	POSSIBLE ALTERATIONS/NOTES	ARCHITECTURAL STYLE	NOTES
1404	N	HOLLISTON AVE	5850-015-003	1923		contributing	windows	Spanish Colonial Revival	Comp shingles original per BDB
1410	N	HOLLISTON AVE	5850-015-002	1940		contributing		English Vernacular	
1415	N	HOLLISTON AVE	5849-007-011	1923		contributing		Mission Revival	
1422	N	HOLLISTON AVE	5850-015-001	1923		contributing		Spanish Colonial Revival	
1425	N	HOLLISTON AVE	5849-007-010	1927	C F. Ericson/Stephen Berczick (architect & builder)	contributing		Spanish Colonial Revival	
1430	N	HOLLISTON AVE	5850-014-018	1923		contributing	wall cladding	Spanish Colonial Revival	
1435	N	HOLLISTON AVE	5849-007-009	1941		contributing	wall cladding	Minimal Traditional	
1438	N	HOLLISTON AVE	5850-014-017	1923		contributing		Spanish Colonial Revival	
1446	N	HOLLISTON AVE	5850-014-016	1923		out of period			New house under const
1450	N	HOLLISTON AVE	5850-014-015	1923		non-contributing	wall cladding; inappropriate addition		1952 Addition
1451	N	HOLLISTON AVE	5849-007-008	1914		contributing		Craftsman Bungalow	
1460	N	HOLLISTON AVE	5850-014-027	1923		contributing	windows	English Vernacular	
1465	N	HOLLISTON AVE	5849-007-007	1928		contributing	wall cladding	Colonial Revival	
1468	N	HOLLISTON AVE	5850-014-012	1942		contributing		Minimal Traditional	
1474	N	HOLLISTON AVE	5850-014-011	1924		contributing	wall cladding	Spanish Colonial Revival	
1477	N	HOLLISTON AVE	5849-007-026	1914		contributing	doors; appropriate addition; windows		
1480	N	HOLLISTON AVE	5850-014-010	1924		contributing		English Vernacular	
1491	N	HOLLISTON AVE	5849-007-004	1925		contributing		Spanish Colonial Revival	
1494	N	HOLLISTON AVE	5850-014-008	1924		non-contributing	windows; doors; roof	Spanish Colonial Revival	
1495	N	HOLLISTON AVE	5849-007-003	1929		non-contributing	windows; wall cladding	Spanish Colonial Revival	
1500	N	HOLLISTON AVE	5850-014-004	1925		contributing	wall cladding	English Vernacular	
1505	N	HOLLISTON AVE	5849-007-002	1924		non-contributing	windows; doors; wall cladding; porch	Craftsman Bungalow	
1506	N	HOLLISTON AVE	5850-014-003	1922		contributing	porch	Craftsman Bungalow	
1511	N	HOLLISTON AVE	5849-007-001	1924		contributing		Spanish Colonial Revival	
1514	N	HOLLISTON AVE	5850-014-002	1914		contributing		Craftsman Bungalow	
1522	N	HOLLISTON AVE	5850-014-001	1915		contributing		Craftsman Bungalow	
1530	N	HOLLISTON AVE	5850-013-011	1916		contributing	windows; wall cladding	Craftsman Bungalow	
1538	N	HOLLISTON AVE	5850-013-010	1915		non-contributing	windows; doors; porch	Craftsman Bungalow	
1546	N	HOLLISTON AVE	5850-013-009	1916		non-contributing	windows; wall cladding; porch	Craftsman Bungalow	
1549	N	HOLLISTON AVE	5849-006-021	1920		contributing		Craftsman Bungalow	
1554	N	HOLLISTON AVE	5850-013-008	1916		contributing	windows; porch; appropriate addition	Spanish Colonial Revival	Date per BDB
1559	N	HOLLISTON AVE	5849-006-004	1924		contributing	windows	Craftsman Bungalow	
1562	N	HOLLISTON AVE	5850-013-007	1916		contributing	windows	English Vernacular	
1567	N	HOLLISTON AVE	5849-006-003	1923		contributing	windows	Craftsman Bungalow	
1570	N	HOLLISTON AVE	5850-013-006	1924		contributing	windows; porch	Spanish Colonial Revival	
1575	N	HOLLISTON AVE	5849-006-002	1923		contributing	wall cladding	Spanish Colonial Revival	
1576	N	HOLLISTON AVE	5850-013-005	1925		contributing	windows	Spanish Colonial Revival	
1588	N	HOLLISTON AVE	5850-013-027	1920		non-contributing	windows; wall cladding; porch; inappropriate addition		
1594	N	HOLLISTON AVE	5850-013-003	1960		out of period	addition	Craftsman Bungalow	
1604	N	HOLLISTON AVE	5850-013-001	1916		non-contributing	wall cladding; porch	Ranch	
1609	N	HOLLISTON AVE	5849-005-029	1926	Virgil A. Rice (architect) / James S. Clime (builder)	contributing		Craftsman Bungalow	
1617	N	HOLLISTON AVE	5849-005-007	1949		contributing		English Vernacular	
1620	N	HOLLISTON AVE	5850-012-001	1926		contributing		Minimal Traditional	
1625	N	HOLLISTON AVE	5849-005-006	1925		contributing			
1631	N	HOLLISTON AVE	5849-005-005	1948		contributing	inappropriate addition	Spanish Colonial Revival	addition in 1960
1637	N	HOLLISTON AVE	5849-005-004	1923		contributing		Spanish Colonial Revival	
1640	N	HOLLISTON AVE	5850-012-008	1923		contributing		English Vernacular	
1645	N	HOLLISTON AVE	5849-005-003	1927		contributing	doors	English Vernacular	
1650	N	HOLLISTON AVE	5850-012-009	1923		contributing		Spanish Colonial Revival	
1653	N	HOLLISTON AVE	5849-005-002	1923		contributing		English Vernacular	
1661	N	HOLLISTON AVE	5849-005-001	1923	Virgil A. Rice (architect)	contributing	appropriate addition	Craftsman Bungalow	
1680	N	HOLLISTON AVE	5850-007-013	1923		contributing		Spanish Colonial Revival	
1695	N	HOLLISTON AVE	5849-004-012	1922		contributing		Spanish Colonial Revival	
1698	N	HOLLISTON AVE	5850-007-014	1926		contributing		Craftsman Bungalow	
1102-4	E	HOWARD AVE	5849-023-014	1912		contributing		Spanish Colonial Revival	

Historic Highlands Inventory

NO	DIR	STREET	APN	DATE	ARCHITECT/BUILDER	STATUS	POSSIBLE ALTERATIONS/NOTES	ARCHITECTURAL STYLE	NOTES
915	E	HOWARD ST	5848-033-002	1922		contributing	windows;doors	Craftsman Bungalow	
921	E	HOWARD ST	5848-033-003	1922		contributing		Colonial Revival	
931	E	HOWARD ST	5848-033-004	1922		non-contributing	porch; inappropriate addition	Craftsman Bungalow	
941	E	HOWARD ST	5848-033-029	1925		contributing		Craftsman Bungalow	Hidden by shrubs
944	E	HOWARD ST	5848-032-007	1913	W. Keift & H.J. Hetherington (architect & builder)	contributing		Craftsman Bungalow	
950	E	HOWARD ST	5848-032-009	1910	F.A. Miller (architect & builder)	non-contributing	porch	Craftsman Bungalow	Porch enclosed in 1920's
953	E	HOWARD ST	5848-033-028	1925	Union Home Building Co.	contributing	windows;doors	English Vernacular	Upper mass added in 1920's
958	E	HOWARD ST	5848-032-010	2000		out of period		Neo-Craftsman	
965	E	HOWARD ST	5848-033-027	1909	G. C. Randall (builder)	contributing		Arts and Crafts	
968	E	HOWARD ST	5848-032-013	1924		contributing	windows;wall cladding	English Vernacular	
973	E	HOWARD ST	5848-033-026	1907	George Helfman (builder)	contributing	windows	Arts and Crafts	
976	E	HOWARD ST	5848-032-014	1924		contributing		English Vernacular	
983	E	HOWARD ST	5848-033-025	1910	Harry O. Clarke (builder)	contributing		Arts and Crafts	
984	E	HOWARD ST	5848-032-015	1907		non-contributing	windows;porch;inappropriate addition	Craftsman Bungalow	1950's addition
990	E	HOWARD ST	5848-032-016	1912	Daniel S. Parker (architect & builder)	contributing		Arts and Crafts	
1004	E	HOWARD ST	5848-032-017	1915	G.V. Barnes (architect)	contributing		Arts and Crafts	
1008	E	HOWARD ST	5848-032-018	1911	G.V. Barnes (architect)	contributing		Craftsman Bungalow	
1025	E	HOWARD ST	5849-022-029	1923		contributing	wall cladding	Minimal Traditional	
1026	E	HOWARD ST	5849-023-001	1914		contributing		Minimal Traditional	
1035	E	HOWARD ST	5849-022-025	1923		contributing	wall cladding	Craftsman Bungalow	
1036	E	HOWARD ST	5849-023-004	1911	J.M. Shannon (builder)	non-contributing	windows;doors;wall cladding;porch	Craftsman Bungalow	
1044	E	HOWARD ST	5849-023-005	1924		non-contributing	windows;wall cladding	English Vernacular	
1045	E	HOWARD ST	5849-022-024	1923		contributing		Minimal Traditional	
1052	E	HOWARD ST	5849-023-006	1940		contributing	windows;doors;porch		
							windows;doors;wall cladding;appropriate addition		
1055	E	HOWARD ST	5849-022-023	1923		non-contributing		Craftsman Bungalow	
1062	E	HOWARD ST	5849-023-007	1912	D. Shilling & L.B. Luce (builder)	non-contributing	windows;doors;wall cladding;porch	Craftsman Bungalow	
1063	E	HOWARD ST	5849-022-022	1963		out of period		Ranch	
1070	E	HOWARD ST	5849-023-008	1923		contributing	wall cladding	Craftsman Bungalow	
1071	E	HOWARD ST	5849-022-021	1924		non-contributing	windows;roof;porch	Minimal Traditional	Porch altered in 1934
1078	E	HOWARD ST	5849-023-009	1912		non-contributing	windows;doors;wall cladding;porch	Craftsman Bungalow	not a good example of ranch style; appears altered
1085	E	HOWARD ST	5849-022-020	1956		non-contributing		Ranch	
1086	E	HOWARD ST	5849-023-011	1901		contributing	porch	Craftsman Bungalow	
1094	E	HOWARD ST	5849-023-012	1912		contributing		Craftsman Bungalow	Unusual plan
1099	E	HOWARD ST	5849-022-019	1922		contributing		Craftsman Bungalow	
1105	E	HOWARD ST	5849-022-018	1923		contributing	wall cladding	Spanish Colonial Revival	
1140	E	HOWARD ST	5849-011-006	1924		contributing		English Vernacular	
1143	E	HOWARD ST	5849-012-022	1923		non-contributing	windows;doors;wall cladding;porch	Spanish Colonial Revival	
1151	E	HOWARD ST	5849-012-012	1913		contributing	porch	Arts and Crafts	
1156	E	HOWARD ST	5849-011-005	1920		contributing		Craftsman Bungalow	
1161	E	HOWARD ST	5849-012-013	1913		contributing		Mediterranean Revival	
1166	E	HOWARD ST	5849-011-004	1921		contributing	roof	Spanish Colonial Revival	
1171	E	HOWARD ST	5849-012-014	1914		contributing		Colonial Revival	
1181	E	HOWARD ST	5849-012-015	1923		contributing	windows;doors	English Vernacular	
1193	E	HOWARD ST	5849-012-016	1913		contributing		Arts and Crafts	
1244	E	HOWARD ST	5849-009-002	1950		contributing		Mid-century Modern	
1245	E	HOWARD ST	5849-006-015	1949		non-contributing	cladding; windows; roof		
1255	E	HOWARD ST	5849-006-016	1927	Henry C. Nickerson (architect)	contributing		Tudor	
1271	E	HOWARD ST	5849-006-017	1912		contributing		Arts and Crafts	
1283	E	HOWARD ST	5849-006-018	1912		contributing	wall cladding	Arts and Crafts	
1290	E	HOWARD ST	5849-007-025	1945		contributing		Minimal Traditional	
1291	E	HOWARD ST	5849-006-019	1916		contributing		Craftsman Bungalow	
1305	E	HOWARD ST	5849-006-020	1916		contributing	doors;porch	Arts and Crafts	
1540	N	LAKE AVE	5848-033-005	1925		contributing	windows	Spanish Colonial Revival	Multi-family
1550	N	LAKE AVE	5848-033-006	1924		contributing		Spanish Colonial Revival	

Historic Highlands Inventory

NO	DIR	STREET	APN	DATE	ARCHITECT/BUILDER	STATUS	POSSIBLE ALTERATIONS/NOTES	ARCHITECTURAL STYLE	NOTES
1564	N	LAKE AVE	5848-033-007	1907		non-contributing	windows;wall cladding;porch	Craftsman Bungalow	
1584	N	LAKE AVE	5848-033-008	1961		out of period		Commercial	Dairy
1612	N	LAKE AVE	5848-034-004	1921		contributing	windows	Craftsman Bungalow	Bungalow court
1628	N	LAKE AVE	5848-034-005	1924		non-contributing	windows	Spanish Colonial Revival	
1632	N	LAKE AVE	5848-034-006	1953		contributing	windows;porch	Minimal Traditional	
1642	N	LAKE AVE	5848-034-007	1923		out of period	windows;doors;wall cladding	English Vernacular	Apartments
1680	N	LAKE AVE	5848-035-025	1963		non-contributing	windows;doors;porch;inappropriate addition	Arts and Crafts	
1710	N	LAKE AVE	5848-035-003	1922		contributing	windows;doors	Minimal Traditional	
1754	N	LAKE AVE	5848-036-023	1946		contributing	wall cladding	Craftsman Bungalow	
1776	N	LAKE AVE	5848-036-024	1921		contributing	porch	Spanish Colonial Revival	
1386		MAR VISTA AVE	5849-010-004	1909		contributing	roof	Colonial Revival	
1394		MAR VISTA AVE	5849-010-003	1922		contributing	windows	Prairie	
1401		MAR VISTA AVE	5849-025-006	1914		contributing		Tudor	
1408		MAR VISTA AVE	5849-010-002	1929		contributing		Arts and Crafts	
1411		MAR VISTA AVE	5849-025-005	1912		contributing	narrow separate parcel, same address as adjacent lot		
1411	N	MAR VISTA AVE	5849-025-004			contributing			
1425		MAR VISTA AVE	5849-025-008	1921		contributing		Prairie	
1447		MAR VISTA AVE	5849-024-027	1922		contributing		English Vernacular	
1450		MAR VISTA AVE	5849-011-011	1923		contributing		Spanish Colonial Revival	
1455		MAR VISTA AVE	5849-024-026	1922		contributing	porch	Colonial Revival	
1460		MAR VISTA AVE	5849-011-010	1922		contributing		Prairie	
1465		MAR VISTA AVE	5849-024-025	1923		non-contributing	doors;wall cladding	Craftsman Bungalow	
1475		MAR VISTA AVE	5849-024-024	1924		contributing		English Vernacular	
1478		MAR VISTA AVE	5849-011-009	1916		contributing	wall cladding	Prairie	
1483		MAR VISTA AVE	5849-024-023	1923		contributing		Spanish Colonial Revival	
1490		MAR VISTA AVE	5849-011-008	1924		contributing		Prairie	
1491		MAR VISTA AVE	5849-023-017	1913	Henry Wilson	contributing	wall cladding	Spanish Colonial Revival	
1495		MAR VISTA AVE	5849-023-016	1914		contributing	windows;porch	Craftsman Bungalow	
1500		MAR VISTA AVE	5849-011-007	1930		contributing		Spanish Colonial Revival	
1501		MAR VISTA AVE	5849-023-015	1914		contributing	porch	Arts and Crafts	
1505		MAR VISTA AVE	5849-023-014	1912		contributing		Craftsman Bungalow	
1525		MAR VISTA AVE	5849-022-017	1923		contributing	windows	Spanish Colonial Revival	
1535		MAR VISTA AVE	5849-022-016	1921		contributing		Craftsman Bungalow	
1547		MAR VISTA AVE	5849-022-015	1925		non-contributing	wall cladding;porch		
1549		MAR VISTA AVE	5849-022-014	1922		contributing		Spanish Colonial Revival	
1550		MAR VISTA AVE	5849-012-021	1961		out of period		Ranch	
1559		MAR VISTA AVE	5849-022-011	1923		contributing		English Vernacular	
1562		MAR VISTA AVE	5849-012-020	1924		contributing		Spanish Colonial Revival	
1567		MAR VISTA AVE	5849-022-012	1924		contributing	windows	English Vernacular	
1625		MAR VISTA AVE	5849-021-016	1925		contributing	windows	Spanish Colonial Revival	
1632		MAR VISTA AVE	5849-013-027	1924		contributing	porch	Spanish Colonial Revival	
1633		MAR VISTA AVE	5849-021-017	1925		contributing		Craftsman Bungalow	
1640		MAR VISTA AVE	5849-013-012	1922		contributing	windows	Spanish Colonial Revival	
1641		MAR VISTA AVE	5849-021-013	1922		contributing		English Vernacular	
1648		MAR VISTA AVE	5849-013-023	1922		contributing		Craftsman Bungalow	
1649		MAR VISTA AVE	5849-021-012	1922		contributing	windows;wall cladding	Craftsman Bungalow	
1659		MAR VISTA AVE	5849-021-011	1921		non-contributing	windows;doors;wall cladding;porch	Spanish Colonial Revival	
1660		MAR VISTA AVE	5849-013-025	1922		contributing		Colonial Revival	
1680		MAR VISTA AVE	5849-014-007	1947		contributing	windows	Minimal Traditional	
1690		MAR VISTA AVE	5849-014-006	1947		contributing	wall cladding	Minimal Traditional	
1700		MAR VISTA AVE	5849-014-005	1950		contributing	windows;doors	Minimal Traditional	
1709		MAR VISTA AVE	5849-020-012	1935		contributing		English Vernacular	
1369	N	MENTOR AVE	5848-029-019	1938	R. J. Edmonton (builder)	contributing		Spanish Colonial Revival	Half-court

Historic Highlands Inventory

NO	DIR	STREET	APN	DATE	ARCHITECT/BUILDER	STATUS	POSSIBLE ALTERATIONS/NOTES	ARCHITECTURAL STYLE	NOTES
1376	N	MENTOR AVE	5848-030-005	1919		contributing		Craftsman Bungalow	
1379	N	MENTOR AVE	5848-029-018	1924	J. G. Dahl & Sons (builder)	contributing	windows	English Vernacular	
1385	N	MENTOR AVE	5848-029-017	1910	Henry C. Deming (architect & builder)	contributing		Craftsman Bungalow	
1386	N	MENTOR AVE	5848-030-004	1914	Eva Sartwell (builder)	contributing		Craftsman Bungalow	
1392	N	MENTOR AVE	5848-030-003	1912	Henry C. Deming/Andrew E. Thompson (architect & builder)	contributing	windows	Craftsman Bungalow	
1393	N	MENTOR AVE	5848-029-016	1924	Edwin A. Eastman (architect?), John Mellema (builder)	non-contributing	windows; wall cladding	Craftsman Bungalow	
1401	N	MENTOR AVE	5848-029-015	1923	E.D. Cappell (builder)	contributing	porch	Spanish Colonial Revival	
1402	N	MENTOR AVE	5848-030-020	1924		non-contributing	wall cladding; inappropriate addition	Craftsman Bungalow	Check permits
1409	N	MENTOR AVE	5848-029-014	1923		contributing		Craftsman Bungalow	
1417	N	MENTOR AVE	5848-029-013	1922	W.L. Bixler (builder)	non-contributing	roof	Spanish Colonial Revival	
1425	N	MENTOR AVE	5848-029-012	1921	H.T. Kemp	contributing		Craftsman Bungalow	
1462	N	MENTOR AVE	5848-031-013	1910	Henry C. Deming (architect & builder)	contributing	doors; porch	Arts and Crafts	
1470	N	MENTOR AVE	5848-031-012	1907	Henry C. Deming (architect & builder)	non-contributing	doors; roof; porch; inappropriate addition	Craftsman Bungalow	
1478	N	MENTOR AVE	5848-031-011	1921		non-contributing	windows; doors; inappropriate addition	Craftsman Bungalow	Original house much smaller; no hist. BPs found
1480	N	MENTOR AVE	5848-032-011	1901		non-contributing	narrow separate parcel; same address as adjacent lot	Craftsman Bungalow	
1480	N	MENTOR AVE	5848-032-012			non-contributing	adjacent lot	Ranch	
1487	N	MENTOR AVE	5848-032-008	1948		contributing	appropriate addition		Can't see
1380	N	MICHIGAN AVE	5849-009-015	1950		contributing			
1385	N	MICHIGAN AVE	5849-010-008	1918		contributing	windows; wall cladding	Craftsman Bungalow	
1399	N	MICHIGAN AVE	5849-010-009	1914		contributing		Arts and Crafts	
1400	N	MICHIGAN AVE	5849-009-028	1924		contributing		Tudor	
1402	N	MICHIGAN AVE	5849-009-027			contributing		N/A	Vacant lot
1415	N	MICHIGAN AVE	5849-010-010	1914	D.M. Renton (architect/contractor)	contributing		Arts and Crafts	
1424	N	MICHIGAN AVE	5849-009-018	1912		contributing		English Vernacular	
1425	N	MICHIGAN AVE	5849-010-011	1917		contributing		Mediterranean Revival	
1436	N	MICHIGAN AVE	5849-009-019	1926		contributing		Spanish Colonial Revival	
1447	N	MICHIGAN AVE	5849-011-012	1914	D.M. Renton (architect/contractor)	contributing	windows	Craftsman Bungalow	
1450	N	MICHIGAN AVE	5849-009-020	1924		contributing		Spanish Colonial Revival	
1460	N	MICHIGAN AVE	5849-009-030	1885	C.C. Thompsen (builder)	contributing		Queen Anne	
1461	N	MICHIGAN AVE	5849-011-013	1923		contributing		Prairie	
1472	N	MICHIGAN AVE	5849-009-022	1924		contributing	windows	English Vernacular	
1475	N	MICHIGAN AVE	5849-011-014	1917		contributing		Colonial Revival	
1480	N	MICHIGAN AVE	5849-009-023	1925	Glen Ellwood Smith (architect)	contributing	windows; doors; wall cladding porch	Colonial Revival	
1485	N	MICHIGAN AVE	5849-011-015	1921	Marston & Van Pelt (verify)	non-contributing	windows; doors; wall cladding porch	Craftsman Bungalow	
1496	N	MICHIGAN AVE	5849-009-024	1924		contributing	appropriate addition	Spanish Colonial Revival	
1499	N	MICHIGAN AVE	5849-011-016	1937		contributing	windows	Mediterranean Revival	
1510	N	MICHIGAN AVE	5849-009-029	1923		contributing		Italian Renaissance Revival	
1531	N	MICHIGAN AVE	5849-012-017	1922		contributing		Spanish Colonial Revival	
1540	N	MICHIGAN AVE	5849-006-014	1930		contributing		Minimal Traditional	
1560	N	MICHIGAN AVE	5849-006-010	1948		contributing		English Vernacular	
1575	N	MICHIGAN AVE	5849-012-023	1926		contributing		Arts and Crafts	
1635	N	MICHIGAN AVE	5849-013-003	1914		non-contributing	wall cladding; porch	Craftsman Bungalow	
1638	N	MICHIGAN AVE	5849-005-017	1923		contributing	windows	Craftsman Bungalow	
1645	N	MICHIGAN AVE	5849-013-002	1923		contributing		English Vernacular	
1655	N	MICHIGAN AVE	5849-013-001	1913		contributing		Spanish Colonial Revival	
1681	N	MICHIGAN AVE	5849-014-025	1924		contributing		Spanish Colonial Revival	
1687	N	MICHIGAN AVE	5849-014-026	1924		contributing	porch	Spanish Colonial Revival	
1695	N	MICHIGAN AVE	5849-014-027	1924		contributing		Spanish Colonial Revival	
932		RIO GRANDE ST	5848-029-011	1923	E.C. Thomas (builder)	contributing		Spanish Colonial Revival	
957		RIO GRANDE ST	5848-031-014	1917	Rufus J. Stukeley (builder)	contributing		Craftsman Bungalow	
965		RIO GRANDE ST	5848-031-015	1918	Rufus J. Stukeley (builder)	contributing		Craftsman Bungalow	
975		RIO GRANDE ST	5848-031-016	1918	Rufus J. Stukeley (builder)	contributing		Craftsman Bungalow	
980		RIO GRANDE ST	5848-030-019	1927		contributing	windows; doors	Church	
981		RIO GRANDE ST	5848-031-017	1922		contributing		Craftsman Bungalow	

Historic Highlands Inventory

NO	DIR	STREET	APN	DATE	ARCHITECT/BUILDER	STATUS	POSSIBLE ALTERATIONS/NOTES	ARCHITECTURAL STYLE	NOTES
990		RIO GRANDE ST	5848-030-011	1922		contributing	wall cladding;porch	Craftsman Bungalow	
991		RIO GRANDE ST	5848-031-021	1922		contributing		Spanish Colonial Revival	
998		RIO GRANDE ST	5848-030-010	1922		non-contributing	windows;wall cladding	Craftsman Bungalow	
999		RIO GRANDE ST	5848-031-022	1924		contributing	windows	Craftsman Bungalow	
1005		RIO GRANDE ST	5848-031-023	1927		contributing		Craftsman Bungalow	
1006		RIO GRANDE ST	5848-030-009	1923		contributing	wall cladding	Craftsman Bungalow	
1025		RIO GRANDE ST	5849-024-004	1921		contributing		Craftsman Bungalow	
1035		RIO GRANDE ST	5849-024-005	1912		contributing	porch	Colonial Revival	Second story added; moved to site
1045		RIO GRANDE ST	5849-024-006	1906		contributing		Craftsman Bungalow	
1051		RIO GRANDE ST	5849-024-010	1920		contributing	porch	Craftsman Bungalow	
1063		RIO GRANDE ST	5849-024-012	1925		contributing	porch	Craftsman Bungalow	
1081		RIO GRANDE ST	5849-024-019	1923		non-contributing	windows;wall cladding	Craftsman Bungalow	
1083		RIO GRANDE ST	5849-024-018	1923		non-contributing	windows;doors;wall cladding	Minimal Traditional	
1095		RIO GRANDE ST	5849-024-020	1923		contributing	wall cladding	Craftsman Bungalow	
1096		RIO GRANDE ST	5849-025-001	1913		contributing	windows;porch	Craftsman Bungalow	Side wdocs vinyl
1097		RIO GRANDE ST	5849-024-021	1922		contributing		Spanish Colonial Revival	
1099		RIO GRANDE ST	5849-024-022	1923		contributing	wall cladding	Spanish Colonial Revival	
1136		RIO GRANDE ST	5849-010-001	1922		contributing	wall cladding	Spanish Colonial Revival	
918		TOPEKA ST	5848-034-008	1924	E. A. Hays Arch Designers/Anna Johnson	contributing		Spanish Colonial Revival	
925		TOPEKA ST	5848-035-026	1916	Godber (H.H.) & Gates (C.C.)	contributing	windows;porch	Arts and Crafts	
930		TOPEKA ST	5848-034-009	1924	E. A. Hays/J.C. Barrington contractor	contributing	windows;wall cladding	Spanish Colonial Revival	Date per permit
935		TOPEKA ST	5848-035-019	1915	Godber (H.H.) & Gates (C.C.)	contributing	wall cladding	Arts and Crafts	
938		TOPEKA ST	5848-034-010	1941		contributing		Minimal Traditional	
945		TOPEKA ST	5848-035-018	1909	Gustav Volkmar	contributing	wall cladding;porch	Arts and Crafts	
946		TOPEKA ST	5848-034-029	1981		out of period		Ranch	
954		TOPEKA ST	5849-034-030	1916	Cyril J. Bennett (architect)/B.O. Kendall. Co. (contractor)	contributing		Craftsman Bungalow	
959		TOPEKA ST	5848-035-017	1914	George Helfman (builder)	contributing		Arts and Crafts	
966		TOPEKA ST	5848-034-012	1925		contributing	windows	English Vernacular	
969		TOPEKA ST	5848-035-016	1914	George Helfman (builder)	contributing		Arts and Crafts	
974		TOPEKA ST	5848-034-013	1926		contributing	appropriate addition	Colonial Revival	
979		TOPEKA ST	5848-035-015	1906		non-contributing	windows;doors;wall cladding;porch;inappropriate addition	Craftsman Bungalow	
984		TOPEKA ST	5848-034-014	1911	George Helfman (builder)	contributing		Craftsman Bungalow	
989		TOPEKA ST	5848-035-014	1921		contributing	windows;doors	Craftsman Bungalow	
992		TOPEKA ST	5848-034-015	1920		non-contributing	porch; wall cladding	Mediterranean Revival	
999		TOPEKA ST	5848-035-013	1921	Foss Designing and Building Company	contributing	windows;doors;porch	Craftsman Bungalow	
1004		TOPEKA ST	5848-034-028	1915	J.P. Bergeron (builder)	contributing		Prairie	
1025		TOPEKA ST	5849-020-022	1924	M. Sabrasky, H.W. Lindsay (architect & builder)	contributing		Monterey Colonial	
1030		TOPEKA ST	5849-021-001	1910	Stimson (architect, attributed) / Carl H. Gustafson (contractor)	contributing		Arts and Crafts	
1040		TOPEKA ST	5849-021-003	1951		contributing		Ranch	
1045		TOPEKA ST	5849-020-021	1925		contributing		Spanish Colonial Revival	
1050		TOPEKA ST	5849-021-004	1906	Robert F. Foss (contractor, attributed)	contributing		Arts and Crafts	
1051		TOPEKA ST	5849-020-027	1952		non-contributing		Ranch/Modern	
1055		TOPEKA ST	5849-020-018	1926		contributing		English Vernacular	
1060		TOPEKA ST	5849-021-005	1920		contributing		Arts and Crafts	
1070		TOPEKA ST	5849-021-006	1918		non-contributing			1955 Permit for major alteration to entrance
1075		TOPEKA ST	5849-020-017	1908	D.J. McPherson	contributing		Shingle	
1080		TOPEKA ST	5849-020-016	1922		contributing		Arts and Crafts	
1085		TOPEKA ST	5849-020-016	1922		contributing	windows	Craftsman Bungalow	
1094		TOPEKA ST	5849-021-008	1934		contributing		English Vernacular	
1095		TOPEKA ST	5849-020-015	1922		contributing	windows	Craftsman Bungalow	
1106		TOPEKA ST	5849-021-009	1942		contributing		Minimal Traditional	
1107		TOPEKA ST	5849-020-014	1923		contributing	windows;roof;wall cladding;porch	Spanish Colonial Revival	
1114		TOPEKA ST	5849-021-010	1921		non-contributing	windows	Spanish Colonial Revival	
1115		TOPEKA ST	5849-020-013	1923		contributing	porch	Spanish Colonial Revival	Pueblo influence - battered walls
1119		TOPEKA ST	5849-020-011	1934		contributing			

Historic Highlands Inventory

NO	DIR	STREET	APN	DATE	ARCHITECT/BUILDER	STATUS	POSSIBLE ALTERATIONS/NOTES	ARCHITECTURAL STYLE	NOTES
1155		TOPEKA ST	5849-014-008	1947		non-contributing	windows; doors; porch	Minimal Traditional	porch added 2004
1160		TOPEKA ST	5849-013-009	1924		non-contributing	landlocked parcel; not visible from street		
1162		TOPEKA ST	5849-013-026	1923		non-contributing	windows; roof; porch	Spanish Colonial Revival	
							narrow separate parcel; same address as adjacent lot		
1162		TOPEKA ST	5849-013-024			non-contributing	windows	Minimal Traditional	
1165		TOPEKA ST	5849-014-009	1947		contributing	windows; doors; wall cladding; porch	Minimal Traditional	
1170		TOPEKA ST	5849-013-007	1923		non-contributing	windows	Craftsman Bungalow	
1175		TOPEKA ST	5849-014-010	1947		contributing	windows; doors; wall cladding; porch	Craftsman Bungalow	
1176		TOPEKA ST	5849-013-006	1928		non-contributing	wall cladding	Arts and Crafts	
1185		TOPEKA ST	5849-014-022	1910		non-contributing	windows; wall cladding; porch	English Vernacular	
1186		TOPEKA ST	5849-013-005	1921		non-contributing	windows; doors; wall cladding; porch	English Vernacular	
1195		TOPEKA ST	5849-014-023	1923		contributing	wall cladding	Craftsman Bungalow	
1198		TOPEKA ST	5849-013-004	1928		contributing	windows	Craftsman Bungalow	
1205		TOPEKA ST	5849-014-024	1924		contributing	doors	Craftsman Bungalow	
1240		TOPEKA ST	5849-005-016	1911		contributing	windows	Craftsman Bungalow	
1241		TOPEKA ST	5849-004-021	1920		contributing	windows	Craftsman Bungalow	
1247		TOPEKA ST	5849-004-020	1921		contributing	windows	Craftsman Bungalow	
1250		TOPEKA ST	5849-005-018	1923		contributing	windows	Craftsman Bungalow	
1257		TOPEKA ST	5849-004-019	1913		contributing	windows	Craftsman Bungalow	
1260		TOPEKA ST	5849-005-019	1942		contributing	windows	Craftsman Bungalow	
1270		TOPEKA ST	5849-005-020	1923		contributing	windows	Craftsman Bungalow	
1273		TOPEKA ST	5849-004-018	1920		contributing	windows	Craftsman Bungalow	
1274		TOPEKA ST	5849-005-021	1923		contributing	windows	Craftsman Bungalow	
1279		TOPEKA ST	5849-004-017	1914		contributing	windows	Craftsman Bungalow	
1286		TOPEKA ST	5849-005-015	1924		non-contributing	windows; doors; roof; porch	Spanish Colonial Revival	Sidelights replaced
1287		TOPEKA ST	5849-004-016	1922		contributing	windows	Craftsman Bungalow	
1294		TOPEKA ST	5849-005-014	1926		contributing	wall cladding	Spanish Colonial Revival	
1295		TOPEKA ST	5849-004-015	1914		contributing	windows	Craftsman Bungalow	
1300		TOPEKA ST	5849-005-013	1924		contributing	windows	Craftsman Bungalow	
1301		TOPEKA ST	5849-004-014	1922		contributing	windows	Craftsman Bungalow	
1307		TOPEKA ST	5849-004-013	1914		contributing	doors; porch	Craftsman Bungalow	
1345		TOPEKA ST	5850-007-015	1923		contributing	doors; porch	Craftsman Bungalow	
1356		TOPEKA ST	5850-012-007	1924		contributing	porch	English Vernacular	
1359		TOPEKA ST	5850-012-006	1924		contributing	windows	Colonial Revival	
1364		TOPEKA ST	5850-007-017	1928		contributing	windows	Craftsman Bungalow	
1365		TOPEKA ST	5850-007-018	1928		contributing	wall cladding	English Vernacular	
1373		TOPEKA ST	5850-007-018	1928		contributing	windows; doors; wall cladding; porch	Arts and Crafts	
969	E	WASHINGTON BLVD	5848-030-008	1911		non-contributing	windows; doors; wall cladding; porch	Craftsman Bungalow	Library
979	E	WASHINGTON BLVD	5848-030-017	1912		contributing	windows; doors; wall cladding; porch	Craftsman Bungalow	Back house to 1070 howard
989	E	WASHINGTON BLVD	5848-030-018	1924		contributing	windows; doors; wall cladding; porch	Craftsman Bungalow	
999	E	WASHINGTON BLVD	5848-030-900	1913		out of period			
1479	E	WILSON AVE	5849-023-008	1923		contributing	windows; doors; wall cladding; porch	Craftsman Bungalow	
1442	N	WILSON AVE	5849-024-017	1923		contributing	windows; doors; wall cladding; porch	Craftsman Bungalow	
1449	N	WILSON AVE	5849-024-011	1925		contributing	windows; doors; wall cladding; porch	Craftsman Bungalow	
1456	N	WILSON AVE	5849-024-016	1922		non-contributing	windows; doors; wall cladding	Craftsman Bungalow	Ranch remodel - 1961
1457	N	WILSON AVE	5849-024-009	1909		contributing	doors	Craftsman Bungalow	
1464	N	WILSON AVE	5849-024-015	1927		non-contributing	windows; doors; wall cladding	Craftsman Bungalow	
1465	N	WILSON AVE	5849-024-008	1920		contributing	windows; doors; wall cladding	Minimal Traditional	
1475	N	WILSON AVE	5849-024-007	1926		contributing	windows; doors; wall cladding	Spanish Colonial Revival	
1476	N	WILSON AVE	5849-024-028	1923		contributing	windows; doors; wall cladding	Spanish Colonial Revival	Hidden; no access from Wilson
1478	N	WILSON AVE	5849-023-013	1927		contributing	windows; doors; wall cladding	Craftsman Bungalow	Min. visible
1480	N	WILSON AVE	5849-023-010	1920		contributing	windows; doors; wall cladding	Craftsman Bungalow	