
















# ATTACHMENT A












**ATTACHMENT B: INVENTORY OF PROPERTIES**

Address	Year Built	Contributing (C) Non-Contributing (NC)	Architectural Style or Reason for Non-Contributing Status	Photo
40 Glen Summer Road	1936	C	Spanish Colonial Revival	
45 Glen Summer Road	1978	NC	Built after the period of significance	
48 Glen Summer Road	1930	C	Spanish Colonial Revival	
51 Glen Summer Road	1930	C	Spanish Colonial Revival	
56 Glen Summer Road	1930	C	Spanish Colonial Revival	
61 Glen Summer Road	1937	C	Colonial Revival Bungalow	
64 Glen Summer Road	1937	NC	Major alterations (replacement windows, infilled front porch and addition of bay windows)	












Address	Year Built	Contributing (C) Non-Contributing (NC)	Architectural Style or Reason for Non-Contributing Status	Photo
70 Glen Summer Road	1939	C	Minimal Traditional Style	
71 Glen Summer Road	1930	C	Spanish Colonial Revival	
77 Glen Summer Road	1947	NC	Built after the period of significance	
80 Glen Summer Road	1948	NC	Built after the period of significance	
85 Glen Summer Road	1947	NC	Built after the period of significance	
90 Glen Summer Road	1947	NC	Built after the period of significance	
95 Glen Summer Road	1937	NC	Minimal Traditional Style (attached garage)	
96 Glen Summer Road	1936	C	Spanish Colonial Revival	












Address	Year Built	Contributing (C) Non-Contributing (NC)	Architectural Style or Reason for Non-Contributing Status	Photo
101 Glen Summer Road	1937	C	Minimal Traditional Style	
104 Glen Summer Road	1937	C	Spanish Colonial Revival	
110 Glen Summer Road	1940	NC	Major Alterations (Addition to front; reconfigured front porch)	
111 Glen Summer Road	1931	C	Spanish Colonial Revival	
119 Glen Summer Road	1927	C	Spanish Colonial Revival (Harold Bissner, Architect)	
127 Glen Summer Road	1927	C	Spanish Colonial Revival (Harold Bissner, Architect)	
128 Glen Summer Road	1928	C	Spanish Colonial Revival (Harold Bissner, Architect)	
135 Glen Summer Road	1927	C	Spanish Colonial Revival (Harold Bissner, Architect)	
136 Glen Summer Road	1928	C	Spanish Colonial Revival (Harold Bissner, Architect)	












Address	Year Built	Contributing (C) Non-Contributing (NC)	Architectural Style or Reason for Non-Contributing Status	Photo
140 Glen Summer Road	1950	NC	Built after the period of significance	
149 Glen Summer Road	1948	NC	Built after the period of significance	
150 Glen Summer Road	1931	C	Spanish Colonial Revival	
159 Glen Summer Road	1938	C	English Cottage Revival	
160 Glen Summer Road	1931	C	Spanish Colonial Revival	
167 Glen Summer Road	1934	C	Spanish Colonial Revival	
168 Glen Summer Road	1930	C	Spanish Colonial Revival	
175 Glen Summer Road	1937	C	Colonial Revival	
176 Glen Summer Road	1930	C	Spanish Colonial Revival	










Address	Year Built	Contributing (C) Non-Contributing (NC)	Architectural Style or Reason for Non-Contributing Status	Photo
184 Glen Summer Road	1930	C	Spanish Colonial Revival	
185 Glen Summer Road	1938	NC	Minimal Traditional Style (attached garage)	
191 Glen Summer Road	1936	NC	Minimal Traditional Style (attached garage)	
192 Glen Summer Road	1930	C	Spanish Colonial Revival	
200 Glen Summer Road	1941	C	Minimal Traditional Style	
201 Glen Summer Road	1936	NC	Modern Ranch Style	
208 Glen Summer Road	1939	C	Minimal Traditional Style	
212 Glen Summer Road	1937	NC	Major alterations – window openings, windows and exterior cladding	
215 Glen Summer Road	1933	C	Spanish Colonial Revival	



Address	Year Built	Contributing (C) Non-Contributing (NC)	Architectural Style or Reason for Non-Contributing Status	Photo
222 Glen Summer Road	1930	C	Tudor	
223 Glen Summer Road	1935	C	Minimal Traditional Style	
231 Glen Summer Road	1935	C	Minimal Traditional Style	
232 Glen Summer Road	1939	C	Colonial Revival	
238 Glen Summer Road	1938	C	Minimal Traditional Style	
239 Glen Summer Road	1932	C	English Cottage Revival	
248 Glen Summer Road	1937	C	Minimal Traditional Style	
254 Glen Summer Road	1933	C	Italian Renaissance Revival	
255 Glen Summer Road	1929	C	Spanish Colonial Revival	



Address	Year Built	Contributing (C) Non-Contributing (NC)	Architectural Style or Reason for Non-Contributing Status	Photo
262 Glen Summer Road	1936	C	English Cottage Revival	
263 Glen Summer Road	1941	C	Colonial Revival Bungalow	
270 Glen Summer Road	1940	NC	Minimal Traditional Style (attached garage)	
271 Glen Summer Road	1937	C	Colonial Revival	
277 Glen Summer Road	1941	NC	Major alterations (incompatible additions, windows, cladding – house was originally one-story and L-shaped)	
280 Glen Summer Road	1930	C	English Cottage Revival	
285 Glen Summer Road	1936	C	Tudor	
1177 Nithsdale Road	1936	NC	Modern Ranch Style	